

Assembly and Operating Manual

MFT-R

Radially compliant pneumatic polishing spindle



Superior Clamping and Gripping



Imprint

Copyright:

This manual is protected by copyright. The author is SCHUNK GmbH & Co. KG. All rights reserved.

Technical changes:

We reserve the right to make alterations for the purpose of technical improvement.

Document number: 1460371

Version: 02.00 | 16/01/2023 | en

Dear Customer,

Thank you for trusting our products and our family-owned company, the leading technology supplier of robots and production machines.

Our team is always available to answer any questions on this product and other solutions. Ask us questions and challenge us. We will find a solution!

Best regards,

Your SCHUNK team

Customer Management

Tel. +49-7133-103-2503

Fax +49-7133-103-2189

cmg@de.schunk.com



Please read the operating manual in full and keep it close to the product.

Table of Contents

1	General.....	5
1.1	About this manual.....	5
1.1.1	Presentation of Warning Labels.....	5
1.1.2	Definition of Terms	6
1.1.3	Applicable documents	6
1.2	Warranty.....	6
1.3	Scope of delivery.....	6
1.4	Accessories.....	6
2	Basic safety notes	7
2.1	Intended use	7
2.2	Not intended use	7
2.3	Constructional changes.....	7
2.4	Spare parts	7
2.5	Ambient conditions and operating conditions.....	8
2.6	Personnel qualification	8
2.7	Personal protective equipment	9
2.8	Transport.....	9
2.9	Malfunctions	9
2.10	Disposal.....	10
2.11	Fundamental dangers	10
2.11.1	Protection during handling and assembly	10
2.11.2	Protection during commissioning and operation	11
2.11.3	Protection against dangerous movements.....	11
2.12	Notes on particular risks	12
3	Technical data.....	13
3.1	Basic data	13
3.2	Compliance force and motor characteristics	14
4	Design and description.....	16
4.1	Design	16
4.2	Description.....	16
5	Assembly and settings	17
5.1	Assembling and connecting	17
5.2	Connections	18
5.2.1	Mechanical connection.....	18
5.2.2	Pneumatic connection	19
5.3	Setting axis fixation	22
5.4	Start-up	23
6	Operation	25

7	Troubleshooting	26
7.1	Tool wears out or breaks	26
7.2	Tool rattles when deburring	26
7.3	Uneven deburring result	27
7.4	Residue on the workpiece after deburring	27
7.5	Tool blocked during machining operation	27
8	Maintenance	28
8.1	Notes.....	28
8.2	Maintenance interval.....	28
8.3	Lubrication of the motor.....	28
8.4	Change tool and collet chuck.....	29
8.5	Change collet chuck holder.....	30
8.6	Changing the spindle boot.....	31
8.7	Changing the motor.....	32
8.8	Replacing the spindle assembly.....	34
8.9	Changing the ring cylinder assembly.....	36
8.10	Assembly drawings.....	37
9	Translation of the original declaration of incorporation	38
10	UKCA declaration of incorporation.....	39
11	Annex to Declaration of Incorporation.....	40

1 General

1.1 About this manual

This manual contains important information for a safe and appropriate use of the product.

This manual is an integral part of the product and must be kept accessible for the personnel at all times.

Before starting work, the personnel must have read and understood this operating manual. Prerequisite for safe working is the observance of all safety instructions in this manual.

In addition to these instructions, the documents listed under ► 1.1.3 [6] are applicable.

NOTE: The illustrations in this manual are intended to provide a basic understanding and may deviate from the actual version.

1.1.1 Presentation of Warning Labels

To make risks clear, the following signal words and symbols are used for safety notes.



⚠ DANGER

Dangers for persons!

Non-observance will inevitably cause irreversible injury or death.



⚠ WARNING

Dangers for persons!

Non-observance can lead to irreversible injury and even death.



⚠ CAUTION

Dangers for persons!

Non-observance can cause minor injuries.

NOTICE

Material damage!

Information about avoiding material damage.

1.1.2 Definition of Terms

The term "product" replaces the product name on the title page in this manual.

1.1.3 Applicable documents

- General terms of business *
- Catalog data sheet of the purchased product *

The documents labeled with an asterisk (*) can be downloaded from [schunk.com](https://www.schunk.com).

1.2 Warranty

If the product is used as intended, the warranty is valid for 24 months from the ex-works delivery date under the following conditions:

- Observe the ambient conditions and operating conditions
- Parts touching the workpiece and wear parts are not included in the warranty.

1.3 Scope of delivery

The scope of delivery includes

- Radially compliant pneumatic polishing spindle MFT-R in the version ordered
- Assembly and Operating Manual
- Accessory pack

Content of the accessory pack:

- Wrench
- (4) M4 x 20 mm cylinder head screws for axle fixation

1.4 Accessories

The following accessories are available for the product, which must be ordered separately:

- Adapter plate
- Spannzangen
- Profilvergöhrung

For information regarding which accessory articles can be used with the corresponding product variants, see catalog data sheet.

2 Basic safety notes

2.1 Intended use

The product is intended exclusively for machining workpieces with a robot.

- The product may only be used within the scope of its technical data, ▶ 3 [□ 13].
- The product is intended for installation in a machine/automated system or for attachment to a robot. The applicable guidelines for the machine/automated system must be observed and complied with.
- The product is intended for industrial and industry-oriented use. Its use outside enclosed spaces is only permitted if suitable protective measures are taken against outdoor exposure. The product is not suitable for use in salty air.
- Appropriate use of the product includes compliance with all instructions in this manual.
- Any utilization that exceeds or differs from the appropriate use is regarded as misuse.

2.2 Not intended use

It is not intended use if the product is used, for example, as a pressing tool, stamping tool, lifting gear, guide for tools, cutting tool, clamping device or a drilling tool.

- Inappropriate use includes using the product as a hand tool.
- Any utilization that exceeds or differs from the appropriate use is regarded as misuse.

2.3 Constructional changes

Implementation of structural changes

By conversions, changes, and reworking, e.g. additional threads, holes, or safety devices can impair the functioning or safety of the product or damage it.

- Structural changes should only be made with the written approval of SCHUNK.

2.4 Spare parts

Use of unauthorized spare parts

Using unauthorized spare parts can endanger personnel and damage the product or cause it to malfunction.

- Use only original spare parts or spares authorized by SCHUNK.

2.5 Ambient conditions and operating conditions

Required ambient conditions and operating conditions

Incorrect ambient and operating conditions can make the product unsafe, leading to the risk of serious injuries, considerable material damage and/or a significant reduction to the product's life span.

- Make sure that the product is used only in the context of its defined application parameters, ▶ 3 [□ 13].

2.6 Personnel qualification

Inadequate qualifications of the personnel

If the personnel working with the product is not sufficiently qualified, the result may be serious injuries and significant property damage.

- All work may only be performed by qualified personnel.
- Before working with the product, the personnel must have read and understood the complete assembly and operating manual.
- Observe the national safety regulations and rules and general safety instructions.

The following personal qualifications are necessary for the various activities related to the product:

Trained electrician

Due to their technical training, knowledge and experience, trained electricians are able to work on electrical systems, recognize and avoid possible dangers and know the relevant standards and regulations.

Qualified personnel

Due to its technical training, knowledge and experience, qualified personnel is able to perform the delegated tasks, recognize and avoid possible dangers and knows the relevant standards and regulations.

Instructed person

Instructed persons were instructed by the operator about the delegated tasks and possible dangers due to improper behaviour.

Service personnel of the manufacturer

Due to its technical training, knowledge and experience, service personnel of the manufacturer is able to perform the delegated tasks and to recognize and avoid possible dangers.

2.7 Personal protective equipment

Use of personal protective equipment

Personal protective equipment serves to protect staff against danger which may interfere with their health or safety at work.

- When working on and with the product, observe the occupational health and safety regulations and wear the required personal protective equipment.
- Observe the valid safety and accident prevention regulations.
- Wear protective gloves to guard against sharp edges and corners or rough surfaces.
- Wear heat-resistant protective gloves when handling hot surfaces.
- Wear protective gloves and safety goggles when handling hazardous substances.
- Wear close-fitting protective clothing and also wear long hair in a hairnet when dealing with moving components.
- Wear ear protection and safety goggles during the machining process.

2.8 Transport

Handling during transport

Incorrect handling during transport can make the product unsafe and risk the danger of serious injuries and considerable material damage.

- During transport and handling, secure the product to prevent it from falling.
- Do not walk under suspended loads.

2.9 Malfunctions

Behavior in case of malfunctions

- Immediately remove the product from operation and report the malfunction to the responsible departments/persons.
- Order appropriately trained personnel to rectify the malfunction.
- Do not recommission the product until the malfunction has been rectified.
- Test the product after a malfunction to establish whether it still functions properly and no increased risks have arisen.

2.10 Disposal

Handling of disposal

The incorrect handling of disposal may impair the product's safety and cause serious injuries as well as considerable material and environmental harm.

- Follow local regulations on dispatching product components for recycling or proper disposal.

2.11 Fundamental dangers

General

- Observe safety distances.
- Never deactivate safety installations.
- Install the provided protective product in the danger zone before switching on the product.
- Remove the energy supplies before installation, modification, maintenance, or adjustment work. Ensure there is no residual energy in the system.
- Do not move parts by hand while the energy supply is connected.
- Do not reach into the movement area of the product during operation.

2.11.1 Protection during handling and assembly

Incorrect handling and assembly

Incorrect handling and assembly may impair the product's safety and cause serious injuries and considerable material damage.

- Have all work carried out by appropriately qualified personnel.
- For all work, secure the product against accidental operation.
- Observe the relevant accident prevention rules.
- Use suitable assembly and transport equipment and take precautions to prevent jamming and crushing.

Incorrect lifting of loads

Falling loads may cause serious injuries and even death.

- Stand clear of suspended loads and do not step into their swiveling range.
- Never move loads without supervision.
- Do not leave suspended loads unattended.

2.11.2 Protection during commissioning and operation

Falling or violently ejected components

Falling and violently ejected components can cause serious injuries and even death.

- Take appropriate protective measures to secure the danger zone.
- Never step into the danger zone during operation.

2.11.3 Protection against dangerous movements

Unexpected movements

Residual energy in the system may cause serious injuries while working with the product.

- Switch off the energy supply, ensure that no residual energy remains and secure against inadvertent reactivation.
- Never rely solely on the response of the monitoring function to avert danger. Until the installed monitors become effective, it must be assumed that the drive movement is faulty, with its action being dependent on the control unit and the current operating condition of the drive. Perform maintenance work, modifications, and attachments outside the danger zone defined by the movement range.
- To avoid accidents and/or material damage, human access to the movement range of the machine must be restricted. Limit/prevent accidental access for people in this area due through technical safety measures. The protective cover and protective fence must be rigid enough to withstand the maximum possible movement energy. EMERGENCY STOP switches must be easily and quickly accessible. Before starting up the machine or automated system, check that the EMERGENCY STOP system is working. Prevent operation of the machine if this protective equipment does not function correctly.

2.12 Notes on particular risks



⚠ DANGER

Risk of fatal injury from suspended loads!

Falling loads can cause serious injuries and even death.

- Stand clear of suspended loads and do not step within their swiveling range.
- Never move loads without supervision.
- Do not leave suspended loads unattended.
- Wear suitable protective equipment.



⚠ WARNING

Risk of injury from objects falling and being ejected!

Falling and ejected objects during operation can lead to serious injury or death.

- Take appropriate protective measures to secure the danger zone.



⚠ WARNING

Risk of injury due to unexpected movements!

If the power supply is switched on or residual energy remains in the system, components can move unexpectedly and cause serious injuries.

- Before starting any work on the product: Switch off the power supply and secure against restarting.
- Make sure, that no residual energy remains in the system.



⚠ CAUTION

Risk of injury from flying chips and dirt particles

During operation, flying chips and dirt particles can cause eye injuries.

- Always wear appropriate personal protective equipment, particularly protective goggles.
- Take suitable protective measures to secure the danger zone.

3 Technical data

3.1 Basic data

Designation	MFT-R
Weight [kg]	4.42
Compensation path X/Y at the collet chuck [mm]	
Recommended	±3.6
Max.	±7.1
Compliance force [N] (radial)	
Min.	9.4
Max.	70
Nominal operating pressure [bar]	
Compensation air connection	1-4.1
Motor air connection	6.2
Pressure medium	Compressed air (clean, dry, filtered ($\leq 5 \mu\text{m}$), oiled)
Max. air consumption [l/s]	9
Oil consumption [drops/min]	3-4
Motor operating data	
Motor	Vane motor (pneumatic)
Idle speed [1/min]	5600
Working speed [RPM]	2600
Power [W]	390
Recommended tool data	
Max. diameter	
Milling head [mm]	17.5
Brush [mm]	75
Max. length [mm]	50

Ambient conditions and operating conditions

Designation	MFT-R
Ambient temperature [°C]	
Min.	+5
Max.	+35

3.2 Compliance force and motor characteristics


NOTE

The compliance force may vary from product to product and should be treated as a guide value only. The actual force characteristics depend on the installation position and the condition of the product. The compliance pressure should be selected depending on the material of the workpiece, the type of tool and the amount of material to be removed.

NOTE

The specified compliance force does not correspond to the actual values when the product is mounted horizontally.

Compensation force




Compensation force as a function of operating pressure

Motor characteristics


NOTE

The working speed of the motor changes in relation to the applied load until the motor has developed the power required to perform the specific task. If no load is applied, the idle speed of the motor is at maximum. When a load is applied, the motor drops to a slower working speed at which the motor develops its maximum power. If the torque required to perform a specific task exceeds the available stall torque, the motor is brought to a standstill. For this reason, multiple, light machining passes are preferred over a single slow machining operation with high infeed and high material removal.



4 Design and description

4.1 Design



1	Compensation air connection
2	Motor air connection
3	Exhaust air silencer
4	Axial Connection
5	Set screw for axis fixation
6	Collet chuck

4.2 Description

Radially compliant pneumatic polishing spindle for polishing and brushing workpieces

5 Assembly and settings

5.1 Assembling and connecting



⚠ WARNING

Risk of injury due to unexpected movements!

If the power supply is switched on or residual energy remains in the system, components can move unexpectedly and cause serious injuries.

- Before starting any work on the product: Switch off the power supply and secure against restarting.
- Make sure, that no residual energy remains in the system.

1. Check the evenness of the mounting surface, ▶ 5.2.1 [□ 18].
2. Attach the product to the robot, ▶ 5.2.1 [□ 18].
 - ✓ If necessary, use appropriate connection elements (adapter plates).
 - ✓ Observe the permissible depth of engagement.
3. Connect compressed air supply, ▶ 5.2.2 [□ 19].
4. If necessary, adjust the axis fixation set screw, ▶ 5.3 [□ 22].

5.2 Connections


5.2.1 Mechanical connection

Evenness of the mounting surface

The values apply to the whole mounting surface to which the product is mounted.

Requirements for evenness of the mounting surface (Dimensions in mm)

Edge length	Permissible unevenness
< 100	< 0.02
> 100	< 0.05



Item	Mounting	MFT-R
1	Mounting screw *	M6
	Max. depth of engagement from locating surface [mm]	10
2	Adapter plate radial *	-
3	Fitting bore for centering pin [mm]	5 ^{H6}
	Max. depth of engagement from locating surface [mm]	8

* Mounting material is not included in the scope of delivery. (available from SCHUNK on request)

5.2.2 Pneumatic connection

NOTICE


Damage to the air hoses possible!

The hoses connected to the air connection spindle can be damaged if the mounting is too tight.

- Allow hoses to hang flexibly so as not to impair the compensating movements of the motor.

NOTE


- Observe the requirements for the compressed air supply, ▶ 3 [13].
 - **For air connection compensation:** For better regulation of the compressed air, use a regulator with air bleed screw.
 - **For air connection motor:** For better regulation of the compressed air, use a 2-way valve and a regulator set at max. 6.2 bar.
 - The vane-type air motor can also be operated at a lower operating pressure to reduce the speed of rotation of the motor. The torque can also be influenced here.
-



1	Compensation air connection
2	Exhaust air silencer
3	Motor air connection

Item	Mounting	MFT-R
1	NPT thread ["]	1/8
	Hose connection [mm]	4
2	NPT thread ["]	1/4
3	NPT thread at the housing ["]	1/4
	Adapter piece with G-thread	1/4

Pneumatics wiring diagram



Pneumatic wiring diagram


5.3 Setting axis fixation

NOTICE

Risk of damage to the product!

A load along the Y-axis when using axis fixation will damage the compensation mechanism.

- When using a single-axis lock, only apply loads in the X direction.
- The product must always be vertical in relation to the edge of the workpiece. Orient the robot appropriately depending on the geometry of the workpiece.



A = 360° compensation, B = compensation in X-axis only

- The product is delivered from the factory with 360° compensation.
 1. Remove the M4 x 20 mm screws from the accessory kit, ► 1.3 [6].
 2. Remove the four M5 x 6 mm screws from the product housing.
 3. Apply threadlocker to the four M4 x 20 mm screws from the accessory kit.
 4. Screw the screws into the holes provided in the housing.
 - ✓ Max. tightening torque: 1.7 Nm
 - ✓ The compensation is only done in x-axis.
 5. Manually check ease of movement and possible directions of movement for correct function.

5.4 Start-up


NOTICE

Risk of damage to the product!

When deburring inner corners or inner radii, the product can be damaged if the cutter touches two edges simultaneously.


- During teach-in, make sure that the cutter never touches two edges simultaneously.
- The inner radius of a burr must never be less than 1.5 times the diameter of the desired cutter.
- After teach-in, increase the feed rate and ensure that the cutter is deflected but remains in contact with the workpiece surface.

Teach-in variant: Dowel Teaching Tool



- For the teach-in process, switch off the motor and apply 0.35 bar to the compensation air connection.
1. Insert a centering pin into the collet chuck instead of a cutter.
 - ✓ The diameter of the centering pin corresponds to the shank diameter of the desired cutter.
 - ✓ Adjust the edge of the centering pin flush with the burr on the workpiece.
 - ✓ The diameter of the cutter is only so much larger than that of the centering pin so that the compensation of the product can compensate for this difference.
 2. Teach-in traverse paths.

**Teach-in variant:
Pointed Teaching
Tool**



- For the teach-in process, switch off the motor and apply 0.35 bar to the compensation air connection.
 1. Insert a specially machined centering pin for the application into the collet chuck instead of a cutter.
 2. Use the center line of the centering pin as a guide and move along the edge of the workpiece.
 3. Add offset manually or automatically to points on the robot path.
 - ✓ The final correct path of the robot was set.

6 Operation

NOTICE

Damage due to axial load!

An axial load on the tool will result in a premature failure of the product.

- Avoid axial loads.
- Avoid loads running parallel to the rotary axis.
- When deburring flat edges, make sure that the tool does not come into contact with material underneath.
- Adjust the infeed so that no more than 30% of the diameter of the cutter is reached.
- When deburring bore holes, guide the cutter in a circular path along the edge of the bore hole. Do not carry out axial infeed (e.g. while lowering), as this will cause an axial force.

NOTICE

Damage to the spindle by coolant!

When using with coolant, ensure that no coolant drips onto the spindle. Dry machining is recommended.

NOTICE

Possible damage to the tool and the tool bearing!

If the tool quickly approaches the workpiece vertically, this will lead to an uneven machining result and premature wear of the bearing and tool.

- Adjust the process parameters precisely.
- Product was completely assembled.
 1. Adjust the robot control system so that the product approaches the workpiece slowly and at a shallow angle.
 2. Adjust feed rate.
 3. Ensure that the distance to the workpiece is correctly adjusted before each new machining operation.
 4. Plan the robot path so that 50% of the compensation function of the product is used at the theoretical tool edge. This allows the product to use its flexibility to machine areas evenly despite different initial geometries without losing contact with the workpiece. If this is not possible, several machining passes may be necessary.
 5. When using the axis fixation, always set the free compensation axis of the product perpendicular to the edge of the workpiece.

7 Troubleshooting

7.1 Tool wears out or breaks

Possible cause	Corrective action
Tool is not suitable for the workpiece.	Select the tool that matches the properties of the workpiece. Coat tool if necessary.
Too much material is being removed.	Check process parameters, reduce infeed, reduce air pressure for compensation, perform machining in several passes., ▶ 6 [□ 25].
The load on the tool is too great because the product is moving too slowly.	Increase feed rate.
Compensation mechanism at the stop.	Readjust the offset, ▶ 6 [□ 25].
High force on initial contact with workpiece.	Change the feed rate and/or angle when approaching the workpiece.
Strong compensation movement at corners.	Use climb milling, approach the workpiece at a more acute angle.

7.2 Tool rattles when deburring

Possible cause	Corrective action
Feed rate not set correctly.	Check process parameters, reduce infeed, reduce air pressure for compensation, perform machining in several passes., ▶ 6 [□ 25].
Compliance pressure too low.	
Too much material is being removed.	
Tool is not suitable for the workpiece.	Select the tool that matches the properties of the workpiece.
Tool is worn out.	Change tool
Spindle assembly is worn.	Check spindle assembly for damage and replace if necessary, ▶ 8.8 [□ 34].

7.3 Uneven deburring result

Possible cause	Corrective action
The pressure valve is defective.	Change pressure valve.
Ring cylinder assembly is damaged.	Check ring cylinder assembly for wear and replace if necessary, ▶ 8.9 [□ 36]

7.4 Residue on the workpiece after deburring

Possible cause	Corrective action
Feed rate not set correctly.	Readjust feed rate.
Tool is worn out.	Change tool
Motor bearings are worn.	Change motor, ▶ 8.7 [□ 32].
Tool is not suitable for the workpiece.	Select the tool that matches the properties of the workpiece.
Too much material is being removed.	Check process parameters, reduce infeed, reduce air pressure for compensation, perform machining in several passes., ▶ 6 [□ 25].
Workpiece is approached too fast or at an incorrect angle.	
Tool clogging with material.	Use another tool, e.g. with fewer teeth.

7.5 Tool blocked during machining operation

Possible cause	Corrective action
Insufficient or no compressed air supply.	Check compressed air lines.
	Check that the pressure valve is set to 6.2 bar. Pressure must be maintained while the spindle is running.
Tool not mounted correctly.	Fasten the tool in the collet chuck.
Workpiece is approached too fast or at an incorrect angle.	Check process parameters, reduce infeed, reduce air pressure for compensation, perform machining in several passes., ▶ 6 [□ 25].
Motor bearings are worn.	Change motor, ▶ 8.7 [□ 32].
Spindle assembly is worn.	Check spindle assembly for damage and replace if necessary, ▶ 8.8 [□ 34].

8 Maintenance

NOTICE

Material damage due to incorrect assembly and disassembly!

Incorrect disassembly and reassembly may cause damage to the product and/or accessories.

- SCHUNK recommends having the product and/or accessories checked and repaired by SCHUNK if necessary.

8.1 Notes

Original spare parts

Use only original spare parts of SCHUNK when replacing spare and wear parts.

8.2 Maintenance interval

Maintenance interval	Maintenance work
daily	Check cutter and collet chuck for damage and wear, replace if necessary, ▶ 8.4 [□ 29].
weekly	Check the collet chuck holder for damage and wear, replace if necessary, ▶ 8.5 [□ 30].
	Check rubber sleeve for damage and wear, replace if necessary, ▶ 8.6 [□ 31].
as required	Change motor, ▶ 8.7 [□ 32]
	Replace spindle assembly, ▶ 8.8 [□ 34].
	Change ring cylinder assembly, ▶ 8.9 [□ 36].
	Send damaged products to SCHUNK for repair.

8.3 Lubrication of the motor

To maximize the service life, only operate the motor for the product with lubrication in the air supply. To do this, lubricate the air supply to the motor with 3-4 drops of a standard pneumatic tool oil per minute.

8.4 Change tool and collet chuck




⚠ WARNING

Risk of burns through contact with hot surfaces!

Surfaces of components can heat up severely during operation. Skin contact with hot surfaces causes severe burns to the skin.


- For all work in the vicinity of hot surfaces, wear safety gloves.
- Before carrying out any work, make sure that all surfaces have cooled down to the ambient temperature.



Change shown on a cutter as an example


1. Remove the compressed air hose.
2. **Bei Tausch durch dasselbe Modell:** Die über die Spannmutter (2) hinausgehende Länge des Werkzeugs (1) messen und notieren.
3. Mit dem 9/16" Schraubenschlüssel aus dem Beipack Spannzangenhalter (4) festhalten.
4. Mit dem 3/4" Schraubenschlüssel aus dem Beipack Spannmutter (2) gegen den Uhrzeigersinn lösen.
5. Ggf. beschädigtes Werkzeug (1) aus der Spannzange ziehen.
6. Ggf. beschädigte Spannzange (3) entfernen und durch eine neue Spannzange ersetzen.
7. **Bei Tausch durch dasselbe Modell:** Freiliegenden Teil des neuen Werkzeugs (1) mit den Daten aus Schritt 2 ausmessen und entsprechend in Spannmutter (2) schieben.
8. Mit kleineren Schraubenschlüssel Spannzangenhalter (4) festhalten.
9. Mit größeren Schraubenschlüssel Spannmutter (2) im Uhrzeigersinn festziehen.
10. Connect all compressed air lines.

8.5 Change collet chuck holder




1. Remove the compressed air hose.
2. Remove the cutter, collet chuck and clamping nut, ► 8.4 [□ 29].
3. Remove M4 screw (4) from spindle assembly.
4. Turn shaft (2) in spindle assembly by hand until locking pin with 3 mm diameter (3) can be inserted in the bore.
 - ✓ Shaft (2) is secured against rotation.
5. Use the 9/16" wrench from the accessory kit to hold the collet chuck holder (1).
6. Turn the new collet chuck holder (1) onto the shaft and tighten it with the wrench.
 - ✓ Max. tightening torque: 5.9 Nm
7. Remove the locking pin (3) from the bore.
8. Screw the M4 screw (4) into the bore provided.
 - ✓ Max. tightening torque: 0.7 Nm
9. Mount the cutter, collet chuck and clamping nut, ► 8.4 [□ 29].
10. Connect all compressed air lines.

8.6 Changing the spindle boot



1. Remove the compressed air hose.
2. Remove the O-ring (1).
3. Loosen the mounting screws (2) and remove the boot ring (3) from the main housing (5).
4. Remove the spindle boot (4).
5. Apply Loctite 222 threadlocker to the mounting screws (2).
6. Install the new spindle boot (4) and boot ring (3) on the main housing (5) using mounting screws (2).
 - ✓ Carefully tighten the screws hand-tight.
7. Tighten O-ring (1) over the spindle boot (4).
8. Connect all compressed air lines.

8.7 Changing the motor




Removing damaged motor

1. Remove the compressed air hose.
2. Remove and store air supply connection and silencer.
3. Thoroughly remove all contamination from the product.
4. Detach the mounting screws (1) and remove the rear housing assembly (2) from the main housing.
5. Detach the mounting screws (3).
6. Screw the set screws (4) in the motor holder into the product to push the motor holder out.
7. Pull motor (6) out of housing.
8. Check whether the elastomer coupling (9) is still seated in the housing, remove if necessary.
9. Hold the flange (7) with a 15 mm wrench and remove the shaft coupling (8).

Inserting the new motor

1. Hold the flange (7) on the new motor with a 15 mm wrench and mount the shaft coupling (8).
 - ✓ Max. tightening torque: 5.9 Nm
2. Fasten the new elastomer coupling (9) on the shaft coupling.
3. Insert the new motor (6) into the housing.
4. Carefully rotate motor until elastomer coupling engages spindle assembly coupling.
5. Unscrew the set screws (4).
6. Apply threadlocker to the mounting screws (1) and (3).
7. Place the motor holder (5) on the housing and tighten the mounting screws (3).
 - ✓ Max. tightening torque: 1.36 Nm
8. Tighten the set screws (4) in the holes provided.
9. Place the rear housing assembly (2) on the housing and fasten with mounting screws (1).
 - ✓ Max. tightening torque: 1.36 Nm
10. Mount the air supply connection and silencer.
11. Connect all compressed air lines.

8.8 Replacing the spindle assembly




Disassembling damaged spindle assembly

1. Remove the compressed air hose.
2. Loosen the screws (7).
3. Unscrew the spindle assembly (1) using a 24 mm wrench.
4. Remove elastomer coupling (6) from spindle assembly.
5. Unscrew and remove the screws (3).
6. Turn shaft (4) in spindle assembly (1) by hand until locking pin with 3 mm diameter (2) can be inserted in the bore.
✓ Shaft (4) is secured against rotation.
7. Disassemble the shaft coupling (5) from the spindle assembly (1) using the wrench from the accessory kit.
8. Remove the cutter and collet chuck, ▶ 8.4 [□ 29].
9. Remove collet chuck holder, ▶ 8.5 [□ 30].

Mounting a new spindle assembly


1. Unscrew and remove screw (3) from new spindle assembly (1).
2. Turn shaft (4) in spindle assembly (1) by hand until locking pin with 3 mm diameter (2) can be inserted in the bore.
 - ✓ Shaft (4) is secured against rotation.
3. Turn the shaft coupling (5) on the spindle assembly using the wrench from the accessory kit.
4. Mount collet chuck holder, ▶ 8.5 [▢ 30].
5. Mount the cutter and collet chuck, ▶ 8.4 [▢ 29].
6. Remove locking pin (2) and screw the screw (3) into spindle assembly (1).
 - ✓ Max. tightening torque: 0.7 Nm
7. Fasten the new elastomer coupling (6) on the shaft coupling (5).
8. Insert new spindle assembly into motor housing (8).
9. Grip the shaft by the collet chuck and turn carefully until the elastomer coupling engages the coupling in the motor housing.
10. Tighten spindle assembly with wrench.
11. Tighten screws (7).
 - ✓ Max. tightening torque: 1.36 Nm
12. Connect all compressed air lines.

8.9 Changing the ring cylinder assembly



1. Remove the compressed air hose.
2. Loosen the mounting screws (1) and disassemble the rear housing assembly (2) from the main housing.
3. Save the O-rings for the assembly of the new ring cylinder.
4. Loosen the mounting screws (4) and disassemble the ring cylinder assembly (3).
5. Lubricate the O-rings in the new ring cylinder assembly and the bore holes in the rear housing assembly.
6. Align the new ring cylinder assembly (3) with the centering bore in the rear housing assembly (2) and slide it carefully into the rear housing assembly.
7. Fasten the ring cylinder assembly (3) in the rear housing assembly (2) with mounting screws (4).
 - ✓ Max. tightening torque: 1.36 Nm
8. Insert O-rings.
9. Place the rear housing assembly (2) on the main housing and fasten with mounting screws (1).
 - ✓ Max. tightening torque: 1.36 Nm
10. Connect all compressed air lines.

8.10 Assembly drawings



10 UKCA declaration of incorporation

in accordance with the Supply of Machinery (Safety) Regulations 2008.

Manufacturer/
Distributor SCHUNK Intec Limited
 Clamping and gripping technology
 3 Drakes Mews, Crownhill
 MK8 OER Milton Keynes

We hereby declare that on the date of the declaration the following partly completed machine complied with all basic safety and health regulations found in the "Supply of Machinery (Safety) Regulations 2008".

The declaration shall be rendered invalid if modifications are made to the product.

Product designation: Radially compliant pneumatic polishing spindle / MFT-R /
 pneumatic

ID number

The partly completed machine may not be put into operation until it has been confirmed that the machine into which the partly completed machine is to be installed complies with the provisions of the "Supply of Machinery (Safety) Regulations 2008".

Applied harmonized standards, especially:

EN ISO 12100:2010 Safety of machinery - General principles for design -
 Risk assessment and risk reduction

The manufacturer agrees to forward on demand the relevant technical documentation for the partly completed machinery in electronic form to national authorities.

The relevant technical documentation according to Annex VII, Part B, belonging to the partly completed machinery, has been created.

Person authorized to compile the technical documentation:
Marcel Machado, address: refer to manufacturer's address



Lauffen/Neckar, January 2023

p.p. Ralf Winkler;
Head of Technology & Engineering,
Mechanics Gripping Systems

11 Annex to Declaration of Incorporation

in accordance with 2006/42/EC, Appendix II, no. 1 B

as well as

in accordance with the Supply of Machinery (Safety) Regulations 2008.

1. Description of the basic safety and health protection requirements, as per 2006/42/EC, Annex I and per the Supply of Machinery (Safety) Regulations 2008, that apply to and are fulfilled for the scope of the incomplete machine:

Product designation	Radially compliant pneumatic polishing spindle
Type designation	MFT-R

To be provided by the System Integrator for the overall machine	↓
Fulfilled for the scope of the partly completed machine	↓
Not relevant	↓


1.1	Essential Requirements		
1.1.1	Definitions		X
1.1.2	Principles of safety integration		X
1.1.3	Materials and products		X
1.1.4	Lighting		X
1.1.5	Design of machinery to facilitate its handling		X
1.1.6	Ergonomics		X
1.1.7	Operating positions		X
1.1.8	Seating		X

1.2	Control Systems		
1.2.1	Safety and reliability of control systems		X
1.2.2	Control devices		X
1.2.3	Starting		X
1.2.4	Stopping		X
1.2.4.1	Normal stop		X
1.2.4.2	Operational stop		X
1.2.4.3	Emergency stop		X
1.2.4.4	Assembly of machinery		X
1.2.5	Selection of control or operating modes		X
1.2.6	Failure of the power supply		X

1.3	Protection against mechanical hazards		
1.3.1	Risk of loss of stability		X
1.3.2	Risk of break-up during operation	X	
1.3.3	Risks due to falling or ejected objects		X
1.3.4	Risks due to surfaces, edges or angles	X	

1.3	Protection against mechanical hazards			
1.3.5	Risks related to combined machinery	X		
1.3.6	Risks related to variations in operating conditions			X
1.3.7	Risks related to moving parts		X	
1.3.8	Choice of protection against risks arising from moving parts			X
1.3.8.1	Moving transmission parts			X
1.3.8.2	Moving parts involved in the process			X
1.3.9	Risks of uncontrolled movements			X
1.4	Required characteristics of guards and protective devices			
1.4.1	General requirements			X
1.4.2	Special requirements for guards			X
1.4.2.1	Fixed guards			X
1.4.2.2	Interlocking movable guards			X
1.4.2.3	Adjustable guards restricting access			X
1.4.3	Special requirements for protective devices			X
1.5	Risks due to other hazards			
1.5.1	Electricity supply	X		
1.5.2	Static electricity	X		
1.5.3	Energy supply other than electricity			X
1.5.4	Errors of fitting		X	
1.5.5	Extreme temperatures			X
1.45.6	Fire			X
1.5.7	Explosion			X
1.5.8	Noise		X	
1.5.9	Vibrations		X	
1.5.10	Radiation	X		
1.5.11	External radiation	X		
1.5.12	Laser radiation	X		
1.5.13	Emissions of hazardous materials and substances	X		
1.5.14	Risk of being trapped in a machine			X
1.5.15	Risk of slipping, tripping or falling			X
1.5.16	Lightning			X
1.6	Maintenance			
1.6.1	Machinery maintenance			X
1.6.2	Access to operating positions and servicing points			X
1.6.3	Isolation of energy sources			X
1.6.4	Operator intervention			X
1.6.5	Cleaning of internal parts			X

1.7	Information			
1.7.1	Information and warnings on the machinery			X
1.7.1.1	Information and information devices			X
1.7.1.2	Warning devices			X
1.7.2	Warning of residual risks			X
1.7.3	Marking of machinery			X
1.7.4	Instructions		X	
1.7.4.1	General principles for the drafting of instructions			X
1.7.4.2	Contents of the instructions			X
1.7.4.3	Sales literature		X	
	The classification from Annex 1 is to be supplemented from here forward.			
2	Supplementary essential health and safety requirements for certain categories of machinery			X
2.1	Foodstuffs machinery and machinery for cosmetics or pharmaceutical products	X		
2.2	Portable hand-held and/or guided machinery	X		
2.2.1	Portable fixing and other impact machinery	X		
2.3	Machinery for working wood and material with similar physical characteristics			X
3	Supplementary essential health and safety requirements to offset hazards due to the mobility of machinery	X		
4	Supplementary essential health and safety requirements to offset hazards due to lifting operations	X		
5	Supplementary essential health and safety requirements for machinery intended for underground work	X		
6	Supplementary essential health and safety requirements for machinery presenting particular hazards due to the lifting of persons	X		



SCHUNK GmbH & Co. KG
Clamping and gripping technology

Bahnhofstr. 106 - 134
D-74348 Lauffen/Neckar
Tel. +49-7133-103-0
Fax +49-7133-103-2399
info@de.schunk.com
schunk.com

Folgen Sie uns | *Follow us*

