

# Power lathe chuck ROTA THW plus Assembly and operating manual

Translation of original operating  
manual

Hand in hand for tomorrow

## Imprint

### Copyright:

This manual is protected by copyright. The author is SCHUNK SE & Co. KG.  
All rights reserved.

### Technical changes:

We reserve the right to make alterations for the purpose of technical improvement.

**Document number:** 0889021

**Version:** 05.00 | 11/01/2024 | en

Dear Customer,

Thank you for trusting our products and our family-owned company, the leading technology supplier of robots and production machines.

Our team is always available to answer any questions on this product and other solutions. Ask us questions and challenge us. We will find a solution!

Best regards,

Your SCHUNK team

Customer Management

Tel. +49-7572-7614-1300

Fax +49-7572-7614-1039

cmm@de.schunk.com



**Please read the operating manual in full and keep it close to the product.**

## Table of Contents

<b>1</b>	<b>General .....</b>	<b>5</b>
1.1	About this manual.....	5
1.1.1	Illustration of warnings .....	5
1.1.2	Applicable documents .....	6
1.2	Warranty .....	6
1.3	Scope of delivery.....	6
<b>2</b>	<b>Basic safety notes.....</b>	<b>7</b>
2.1	Appropriate use .....	7
2.2	Inappropriate use .....	7
2.3	Structural changes.....	8
2.4	Spare parts .....	8
2.5	Ambient conditions and operating conditions .....	8
2.6	Material limitations .....	8
2.7	Chuck Jaws .....	9
2.8	Personnel qualifications .....	9
2.9	Personal protective equipment .....	10
2.10	Transport.....	10
2.11	Protection during handling and assembly .....	10
2.12	Protection during commissioning and operation .....	10
2.13	Notes on safe operation.....	10
2.14	Disposal .....	13
2.15	Fundamental dangers .....	13
2.16	Protection against dangerous movements .....	13
2.17	Notes on particular risks .....	14
<b>3</b>	<b>Technical data .....</b>	<b>17</b>
3.1	Chuck data .....	17
3.2	Clamping force / speed diagrams .....	17
3.3	Calculations for clamping force and speed .....	20
3.3.1	Calculation of the required clamping force in case of a given rpm.....	20
3.3.2	Calculation example: required initial clamping force for a given speed ..	22
3.3.3	Calculation of the permissible speed in case of a given initial clamping force .....	23
3.4	Grades of Accuracy .....	24
3.5	Permissible imbalance .....	24
<b>4</b>	<b>Attachment and disassembly of the chuck .....</b>	<b>25</b>
4.1	Torques per screw .....	25
4.2	Pre-assembly measures .....	25

4.3 Mounting of the Chuck to the Machine Spindle .....	25
4.4 Disassembling and assembling the chuck .....	29
<b>5 Function and handling .....</b>	<b>32</b>
5.1 Function of the chuck .....	32
5.2 Handling the chuck and the base jaws.....	32
5.3 Base jaw position.....	33
5.4 Change or supplement of jaws .....	33
<b>6 Maintenance .....</b>	<b>34</b>
6.1 Lubrication .....	34
6.2 Maintenance and lubrication plan .....	35
<b>7 Storage.....</b>	<b>36</b>
<b>8 Disposal .....</b>	<b>37</b>
<b>9 Chuck mounts and parts list.....</b>	<b>38</b>
9.1 Chuck mounts .....	38
9.2 Parts list.....	38
<b>10 Drawings .....</b>	<b>40</b>

# 1 General

## 1.1 About this manual

This manual contains important information for the safe, correct use of the product.

It is an integral part of the product and must be kept accessible for personnel at all times.

Personnel must have read and understood this manual before beginning any work. The observance of all safety notes in this manual is a prerequisite to ensure safe work processes.

The illustrations are intended to provide a basic understanding and may deviate from the actual version.

Besides this manual, other documents which apply are those listed under ▶ 1.1.2 [ 6 ]

### 1.1.1 Illustration of warnings

To make risks clear, the following signal words and symbols are used for safety notes.



#### **⚠ DANGER**

Denotes a hazard with a high degree of risk that, if not avoided, will result in death or serious injury.



#### **⚠ WARNING**

Denotes a hazard with a medium degree of risk that, if not avoided, could result in death or serious injury.



#### **⚠ CAUTION**

Denotes a hazard with a low degree of risk that, if not avoided, could result in a minor or moderate injury.

#### **CAUTION**

Information about avoiding material damage.

### 1.1.2 Applicable documents

- General Terms and Conditions \*
- Calculation of the jaw centrifugal forces and jaw guidance load, in the "Technology" chapter of the lathe chuck catalog \* and the "Calculating the clamping force and RPM" chapter
- Brief operating instructions if available
- Approval drawings

The documents labeled with an asterisk (\*) can be downloaded from **schunk.com**.

### 1.2 Warranty

The warranty for standard products is 24 months from the date of delivery from the factory, or 50,000 cycles\* for manually operated clamping devices and 500,000 cycles\* for power operated clamping devices. For special clamping devices, it is 12 months from the date of delivery from the factory, assuming appropriate use in accordance with the following conditions:

- Observe the applicable documents, ▶ 1.1.2 [ 6 ]
- Observance of the ambient conditions and operating conditions, ▶ 2.5 [ 8 ]
- Observance of the specified maintenance and lubrication intervals ▶ 6.2 [ 35 ]

Parts touching the workpiece and wearing parts are not part of the warranty.

\* One cycle comprises one complete clamping procedure ("opening" and "closing")

### 1.3 Scope of delivery

- 1 Power lathe chuck ROTA THW plus
- 1 Set of base jaws
- 3 Mounting screws
- 1 Jaw change key
- 1 Assembly and Operating Manual
- 1 Short operating manual
- 1 Mounting wrench (from size 260)

## 2 Basic safety notes

Improper handling, assembly and maintenance of this product may result in risk to persons and equipment if this operating manual is not observed.

### 2.1 Appropriate use

- The product is used for clamping metal and plastic workpieces on machine tools.
- The product may only be used within the scope of its technical data.
- The product is intended for industrial and commercial use.
- Appropriate use of the product includes compliance with all instructions in this manual.
- The maximum speed and the necessary clamping force must be determined by the operator for each clamping task in accordance with the valid standards or technical specifications of the manufacturer.  
(See also "Calculation for clamping force and speed of rotation" in the chapter "Technical data").
- Use suitable top jaws with a suitable interface.
- The interference circuit diameter of the workpiece must be smaller or at most equal to the outer diameter of the clamping device.
- The workpiece must not experience plastic deformation under clamping force (clamping pressures are permissible).

### 2.2 Inappropriate use

The product is not being used appropriately if:

- the product is used as a press, a punch, a toolholder, a load-handling device or as lifting equipment.
- the specified technical data for use of the product are exceeded.
- workpieces are not properly clamped, paying particular attention to the specified clamping forces.
- the top jaws are not mounted properly.
- the product is not being operated properly.
- the product is operated in the stroke end positions.
- the guideways are overloaded due to the chuck jaws being too high or the clamping point being selected too high.
- the product has been insufficiently maintained.
- the product is brought into contact with aggressive media, especially acids.
- the product is used in abrasive blasting processes, especially sandblasting.

## 2.3 Structural changes

### Implementation of structural changes

Modifications, changes or reworking, e.g. additional threads, holes, or safety devices, can damage the product or impair its functionality or safety.

- Structural changes should only be made with the written approval of SCHUNK.

## 2.4 Spare parts

### Use of unauthorized spare parts

Using unauthorized spare parts can endanger personnel and damage the product or cause it to malfunction.

- Only use original spare parts and spares authorized by SCHUNK.

## 2.5 Ambient conditions and operating conditions

### Required ambient conditions and operating conditions

Incorrect ambient and operating conditions can make the product unsafe, leading to the risk of serious injuries, considerable material damage and/or a significant reduction in the service life of the product.

- Make sure that the product is only used within its defined application parameters.
- Ensure that the product is of a sufficient size for the application.
- Ensure that maintenance and lubricating intervals are observed.
- Only use cooling emulsions with anti-corrosive additives when machining.

Depending on the operating conditions, the function and clamping force must be checked after a certain period of operation .

With the smallest possible actuation pressure on the clamping cylinder, the base jaws should move evenly. This method is not a substitute for measuring the clamping force.

If the clamping force has dropped too much or if the base jaws and/or the release mechanism no longer move properly, the clamping device must be disassembled, cleaned, and relubricated.

## 2.6 Material limitations

The product is made of steel alloys, elastomers, aluminum alloys and brass. In addition, Linomax plus grease, Branotect anti-rust oil and Renolit HLT2 are incorporated into the product as auxiliary and operating materials. The safety data sheet for LINOMAX plus can be found at [www.schunk.com](http://www.schunk.com).

## 2.7 Chuck Jaws

### Requirements of the chuck jaws

Rotational or if applicable, accumulated energy, can make the product unsafe and risk the danger of serious injuries and considerable material damage.

- Change chuck jaws at a standstill and without a clamped workpiece.
- Do not use welded jaws.
- Design the chuck jaws to be as light and as low as possible. The clamping point must be as close as possible to the chuck face (clamping points at a greater distance lead to greater surface pressure in the jaw guidance and can significantly reduce the clamping force).
- If the clamping point is at a greater distance from the housing, the operating pressure must be reduced.
- After a collision, the clamping device and the chuck jaws must be subjected to a crack detection test before being used again. Replace damaged parts with original SCHUNK spare parts.
- The chuck jaw mounting screws and if present, the T-nuts, must be replaced if there are signs of wear or damage. Only use screws of quality grade 12.9 in compliance with the specified tightening torques. For clamping devices with fine serration, the jaw mounting screws must be screwed into the holes closest to the clamping point.

## 2.8 Personnel qualifications

### Inadequate qualification of personnel

Any work on the product by inadequately qualified personnel can lead to serious injuries and considerable material damage.

- All work must be performed by appropriately qualified personnel.
- Personnel must have read and understood the complete manual before beginning any work on the product.
- Observe country-specific accident prevention regulations and the general safety notes.

The following personnel qualifications are required for the various activities on the product:

#### Qualified electrician

Qualified electricians have the professional training, knowledge, and experience to work on electrical systems, to recognize and avoid potential dangers, and know the relevant standards and regulations.

#### Specialist personnel

Specialist personnel have the specialized training, knowledge, and experience to perform the tasks entrusted to them, to recognize and avoid potential dangers, and know the relevant standards and regulations.

**Instructed person** Instructed persons have been instructed by the operator regarding the tasks entrusted to them and the potential dangers of inappropriate behavior.

**Manufacturer's service personnel** The manufacturer's service personnel have the specialized training, knowledge, and experience to perform the work entrusted to them and to recognize and avoid potential dangers.

## 2.9 Personal protective equipment

### Use of personal protective equipment

Personal protective equipment serves to protect staff in the event of a danger that may interfere with their health or safety at work.

## 2.10 Transport

### Handling during transport

Incorrect handling during transport can make the product unsafe and risks the danger of serious injuries and considerable material damage.

- During transport and handling, secure the product to prevent it from falling.
- Use the transport thread on the clamping device.

## 2.11 Protection during handling and assembly

### Incorrect handling and assembly

Incorrect handling and assembly can make the product unsafe and can risk the danger of serious injuries and considerable material damage.

- All work must only be performed by appropriately qualified personnel.
- Secure the system against accidental operation during all work.
- Use suitable assembly and transport equipment and take precautions to prevent jamming and crushing.

## 2.12 Protection during commissioning and operation

### Falling or violently ejected components

Falling and ejected components can lead to serious injury or death.

- Take suitable protective measures to secure the danger zone.

## 2.13 Notes on safe operation

### Incorrect manner of working by personnel

An incorrect manner of working can make the product unsafe and risks serious injuries and considerable material damage.

- Observe the safety notes and assembly instructions.
- Do not expose the product to any corrosive media. Products for special ambient conditions are excluded.

- Rectify malfunctions as soon as they occur.
- Observe the care and maintenance instructions.
- Observe the current safety, accident prevention, and environmental protection regulations for the application field of the product.
- Do not start the machine spindle until the clamping force has built up on the chuck jaws and clamping has taken place in the permissible operating range.
- Unclamping may only occur once the machine spindle has come to a standstill.

### Functionality check

After installation of the clamping device, its function must be checked prior to commissioning.

#### Two important points are:

- **Clamping force:** At max. actuation force/pressure/torque, the clamping force specified for the clamping device must be reached.
- **Stroke control:** The stroke of the clamping piston must have a margin of safety at the front and back end positions. The machine spindle must not start up until the clamping piston has passed through this safety margin.

With manual clamping devices, stroke control is carried out via the indicator pin. Clamping is only correct if the indicator pin is countersunk and clamping force is applied to the workpiece.

When determining the clamping force required to machine a workpiece, the centrifugal force acting on the chuck jaws must be taken into account (according to VDI 3106). If the chuck jaws are changed, the stroke control will have to be adjusted to the new situation.

### Maintenance instructions


The clamping device's reliability and safety can only be guaranteed if the operator complies with the manufacturer's maintenance instructions.

- For lubrication, we recommend our tried and tested special grease, LINOMAX plus. Unsuitable lubricants can have a negative impact on the functioning of the clamping device (clamping force, coefficient of friction, wear behavior). (For product information about LINOMAX plus, see the "Accessories" chapter of the SCHUNK lathe chuck catalog or contact SCHUNK.)
- Use a suitable high-pressure grease gun to ensure that you reach all the greasing areas.
- To ensure correct distribution of the grease, move the clamping device to its end positions several times, lubricate again, and then check the clamping force.

- Move the clamping device through to its end position several times after 500 clamping strokes, at the latest. This moves the lubricant back to the surfaces of the force transmission.
- Check the clamping device regularly for clamping force and jaw stroke.

**Clamping force measurement**

- Depending on the operating conditions, the function and clamping force must be checked after a certain period of operation . For this purpose, a calibrated clamping force meter (e.g. SCHUNK IFT) must be used. The loading conditions are shown below for the different chuck variants.



<b>Measuring device</b>	SCHUNK IFT clamping force tester	SCHUNK IFT clamping force tester	SCHUNK IFT clamping force tester	SCHUNK IFT clamping force tester
<b>Accessories</b>	-	-	IFT MA4	-
<b>Measuring points</b>	0°/180°	0°/120°/240°	0° / 180° / 90° / 270° (IFT MA4)	0°/60°/120°/180°/240°/300°
<b>Please note</b>	Operating manual SCHUNK IFT Clamping force tester	Operating manual SCHUNK IFT Clamping force tester	Operating manual SCHUNK IFT Clamping force tester	Operating manual SCHUNK IFT Clamping force tester
			<b>Attention</b> Compensation must be activated, otherwise it may lead to inconsistent results.	<b>Attention</b> Compensation must be activated, otherwise it may lead to inconsistent results.

- ① Measuring head
- ② Clamping insert
- ③ Chuck jaw
- ④ Bridge element (IFT MA4)

- If the clamping force has dropped too much or if the base jaws and piston no longer move properly, the chuck will have to be disassembled, cleaned and relubricated.
- The clamping force should always be measured with the clamping device in the same condition as it is used in for the current clamping application. If top jaws with clamping steps are used, measuring must be performed in the same step as for the respective clamping task. In the event of high

operating speeds, clamping force losses must be accounted for due to the centrifugal force acting on the chuck jaws. In this case the value of the operating clamping force should be measured dynamically.

- We recommend checking the clamping force using a clamping force tester before starting a new production run and between maintenance intervals. "Optimum safety can only be guaranteed through regular checks".

## 2.14 Disposal

### Handling of disposal

Incorrect handling of disposal can make the product unsafe and lead to risks of environmental harm.

- Follow local regulations on dispatching product components for recycling or proper disposal.

## 2.15 Fundamental dangers

### General

- Disconnect power sources before installation, modification or calibration. Ensure that no residual energy remains in the system.
- Do not reach into the open mechanism or movement area of the product during operation.

## 2.16 Protection against dangerous movements

### Unexpected movements

If the system still retains residual energy, serious injuries can be caused while working on the product.

- Switch off the energy supply, ensure that no residual energy remains and secure against inadvertent reactivation.
- Never rely merely on the response of the monitoring function to avert danger. Assume that the drive movement is faulty as long as the installed monitors are not effective, since the effect depends on the control and the current operating state of the drive.
- To avoid accidents and/or material damage, human access to the movement range of the machine must be restricted.

## 2.17 Notes on particular risks



### **⚠ DANGER**

**Risk of fatal injury to operating personnel due to the workpiece falling down or being flung out in the event of a power failure**

This poses a risk of death or injury to the operating personnel and can result in serious damage to the machine.



### **⚠ DANGER**

**Possible risk of death for the operating personnel in case of insufficient clamping force due to ejection or falling of the workpiece!**

Due to settling behavior, the clamping force may decrease over time.

- Re-clamping of the workpiece with manual or pneumatic clamping devices after 4 hours.
- The energy supply must be constantly applied to power-operated clamping devices during operation.
- Use clamping cylinders with energy conservation.



### **⚠ DANGER**

**Possible risk of death for operating personnel if the clamping device's top speed of rotation is exceeded and a workpiece is released or parts fly off.**

If the machine tool or the technical equipment can reach a higher speed than the maximum speed of the clamping device, the speed must be limited for safety purposes!



### **⚠ DANGER**

**Possible risk of death for operating personnel if a jaw breaks or if the clamping device fails because the technical data has been exceeded and a workpiece is released or parts fly off!**

- Never exceed the technical data specified by the manufacturer for using the clamping device.



### **⚠ DANGER**

**Possible risk of death for operating personnel from clothing or hair getting caught on the clamping device and being dragged into the machine!**

Loose clothing or long hair may become caught on projecting parts of the clamping device and be drawn into the machine.

- Always wear tight-fitting clothing and a hairnet when working on the machine and the lathe chuck.



### **⚠ WARNING**

**Possible risk of death for the operating personnel due to impact of the rotating clamping device!**

- Keep a safe distance to the rotating clamping device!
- Do not reach into the rotating clamping device!



### **⚠ CAUTION**

**Risk of limbs being crushed when opening and closing the chuck jaws during manual loading or unloading or when exchanging moving parts.**

- Do not reach between the chuck jaws.



### **⚠ CAUTION**

**Hazard from vibration due to imbalanced rotating parts and noise generation.**

Physical and mental strains due to imbalanced workpieces and noise during the machining process on the clamped and rotating workpiece.

- Ensure the clamping device's axial and concentric runout.
- Check options for remedying imbalances on special top jaws and workpieces.
- Reduce the speed.
- Wear hearing protection.



### **⚠ CAUTION**

**There is a risk of limbs being crushed by moving parts during manual loading and unloading and the clamping procedure.**

- Do not reach between the chuck jaws.
- Use loading devices.



### **⚠ CAUTION**

**Allergic reactions or irritation due to skin or eye contact with lubricants on the product.**

- In case of foreseeable contact with lubricants on the product (e.g. when lubricating or cleaning)
- Wear protective equipment (protective gloves, protective goggles)

### **CAUTION**

**Risk of damage due to incorrect choice of clamping position for chuck jaws on workpiece.**

If an incorrect clamping position is chosen for the chuck jaws on the workpiece, the base and top jaws may become damaged.

- Observe maximum positions of base and top jaws.
- The diameter of the workpiece must not be greater than the clamping device diameter.
- For clamping devices with fine serration, do not allow the T-nuts for connecting the top jaws to protrude beyond the base jaws in radial direction.
- The outer diameter of the screwed-on top jaws must not exceed the outer diameter of the clamping device by more than 10%.

### 3 Technical data

#### 3.1 Chuck data

ROTA THW plus	165-43	185-52	215-66	260-81	315-104
Max. actuating force [kN]	30	36	46	65	90
Max. clamping force [kN]	45	64	82	115	160
Max. speed of rotation [RPM]	6000	5700	5400	4000	3600
Stroke per jaw [mm]	5.9	6.7	7.4	8.2	8.6
Piston stroke [mm]	20	23	25	28	28
Through hole [mm]	43	52	66	81	104
Weight [kg]	14	18	26	45	70
Operating temperature	15 – 60°C				
Centrifugal torque of the base jaw with fine serration $M_{cGB}$ [kgm]	For the THW plus chuck, it is necessary to specifically determine this data. Examples of calculation can be found in the "Technology" chapter of the SCHUNK lathe chuck catalog and in the "Chuck jaws in special design/ technology" chapter of the SCHUNK chuck jaws catalog. These catalogs can be downloaded at <a href="http://www.schunk.com">www.schunk.com</a> .				

The maximum permissible speed for special machining has to be defined by the user on the basis of the required clamping forces. This speed must not exceed the maximum speed of the chuck.

Ensure minimal weight for all jaws.

For unhardened top jaws or chuck jaws in special design, the permissible RPM according to VDI 3106 must be calculated for the respective machining job. Whereby the recommended maximum speed must not be exceeded. The values calculated must be checked by means of dynamic measurement using a clamping force tester.

#### 3.2 Clamping force / speed diagrams


The diagrams refer to 3-jaw-chuck.

Clamping force/RPM curves have been determined by using hard jaws. In the determination process, the maximum actuating force was applied and the jaws were set flush with the outer diameter of the chuck.

The chuck is in perfect condition and lubricated with SCHUNK LINOMAX plus special grease.


If one or more of these prerequisites is altered, the diagrams will no longer be valid.

### Chuck setup for clamping force/RPM diagram




$F_{spB}$	Clamping force per jaw	$F_{max}$	Max. actuating force
$r_s$	Center of gravity radius	S	Center of gravity


### Clamping force / speed diagrams ROTA THW plus 165-43




### Clamping force / speed diagrams ROTA THW plus 185-52




### Clamping force / speed diagrams ROTA THW plus 215-66



### Clamping force / speed diagrams ROTA THW plus 260-81



### Clamping force / speed diagrams ROTA THW plus 315-104



### 3.3 Calculations for clamping force and speed

Missing information or specifications can be requested from the manufacturer.

Legend			
$F_c$	Total centrifugal force [N]	$M_{cAB}$	Centrifugal torque of top jaws [Kgm]
$F_{sp}$	Effective clamping force [N]	$M_{cGB}$	Centrifugal torque of base jaws [Kgm]
$F_{spmin}$	Minimum required clamping force [N]	n	Speed [rpm]
$F_{sp0}$	Initial clamping force [N]	$r_s$	Center of gravity radius [m]
$F_{spz}$	Cutting force [N]	$r_{sAB}$	Center of gravity radius of top jaw [m]
$m_{AB}$	Mass of one top jaw [kg]	$s_{sp}$	Safety factor for clamping force
$m_B$	Mass of chuck jaw set [kg]	$s_z$	Safety factor for machining
$M_c$	Centrifugal force torque [Kgm]	$\Sigma_s$	Max. clamping force of chuck [N]

#### 3.3.1 Calculation of the required clamping force in case of a given rpm

The initial clamping force  $F_{sp0}$  is the total force impacting radially on the workpiece via the jaws due to actuation of the lathe chuck during shutdown. Under the influence of rotation, the jaw mass generates an additional centrifugal force. The centrifugal force reduces or increases the initial clamping force depending on whether gripping is from the outside inwards or from the inside outwards.

The sum of the initial clamping force  $F_{sp0}$  and the total centrifugal force  $F_c$  is the effective clamping force  $F_{sp}$ .

$$F_{sp} = F_{sp0} \mp F_c \text{ [N]}$$

(-) for gripping from the outside inwards


(+) for gripping from the inside outwards



#### **⚠ DANGER**

Risk to life and limb of the operating personnel and significant property damage when the RPM limit is exceeded! With gripping from the outside inwards, and with increasing RPM, the effective clamping force is reduced by the magnitude of the increasing centrifugal force (the forces are opposed). When the RPM limit is exceeded, the clamping force drops below the required minimum clamping force  $F_{spmin}$ . Consequently, the workpiece is released spontaneously.

- Do not exceed the calculated RPM.
- Do not fall below the necessary minimum clamping force.



Reduction in effective clamping force by the magnitude of the total centrifugal force, for gripping from the outside inwards.

The required effective clamping force for machining  $F_{sp}$  is calculated from the product of the **machining force**  $F_{spz}$  and the **safety factor**  $S_z$ . This factor takes into account uncertainties in the calculation of the machining force. According to VDI 3106:  $S_z \geq 1.5$ .

$$F_{sp} = F_{spz} \cdot S_z \text{ [N]}$$

From this we can derive the calculation of the initial clamping force during shutdown:

$$F_{sp0} = S_{sp} \cdot (F_{sp} \pm F_c) \text{ [N]}$$

(+) for gripping from the outside inwards

(-) for gripping from the inside outwards

**CAUTION**

This calculated force must not be larger than the maximum clamping force  $\Sigma S$  engraved on the lathe chuck.

See also "Lathe chuck data" table ▶ 3.1 [17]

From the above formula it is evident that the sum of the effective clamping force  $F_{sp}$  and the total centrifugal force  $F_c$  is multiplied by the **safety factor for the clamping force**  $S_{sp}$ . According to VDI 3106, the following also applies here:  $S_{sp} \geq 1.5$ .

The **total centrifugal force**  $F_c$  is dependent on both the sum of the masses of all jaws and on the center of gravity radius and the rpm.

**CAUTION**

For safety reasons, in accordance with DIN EN 1550, the centrifugal force may be a maximum of 67% of the initial clamping force.

The formula for the calculation of the total centrifugal force  $F_c$  is:

$$F_c = \sum(m_B \cdot r_s) \cdot \left(\frac{\pi \cdot n}{30}\right)^2 = \sum M_c \cdot \left(\frac{\pi \cdot n}{30}\right)^2 \text{ [N]}$$

For this, **n is the given speed of rotation** in RPM. The product  $m_B \cdot r_s$  is referred to as the centrifugal torque  $M_c$ .

$$M_c = m_B \cdot r_s \text{ [kgm]}$$

In case of toolholders with split chuck jaws, i.e., with base jaws and top jaws, for which the base jaws change their radial position only by the stroke amount, the **centrifugal torque of the base jaws  $M_{cGB}$**  and the **centrifugal torque of the top jaws  $M_{cAB}$**  need to be added:

$$M_c = M_{cGB} + M_{cAB} \text{ [kgm]}$$

The centrifugal torque of the base jaws  $M_{cGB}$  can be found in the table "Lathe chuck data" ▶ 3.1 [17]. The centrifugal torque of the top jaws  $M_{cAB}$  is calculated as per:

$$M_{cAB} = m_{AB} \cdot r_{sAB} \text{ [kgm]}$$

### 3.3.2 Calculation example: required initial clamping force for a given speed

**Required initial clamping force  $F_{sp0}$  for a given RPM n**

The following data is known for the machining job:

- Gripping from the outside in (application-specific)
- Machining force  $F_{spz} = 3000 \text{ N}$  (application-specific)
- max. RPM  $n_{max} = 3200 \text{ RPM}$  ("Lathe chuck data" table)
- RPM  $n = 1200 \text{ RPM}$  (application-specific)
- Mass of one (!) top jaw  $m_{AB} = 5.33 \text{ kg}$  (application-specific)
- Center of gravity radius of top jaw  $r_{sAB} = 0.107 \text{ m}$  (application-specific)
- Safety factor  $S_z = 1.5$  (according to VDI 3106)
- Safety factor  $S_{sp} = 1.5$  (according to VDI 3106)

**Note:** Masses of the jaw mounting screws and T-nuts are not taken into account.

First the required effective clamping force  $F_{sp}$  is calculated using the machining force stated:

$$F_{sp} = F_{spz} \cdot S_z = 3000 \cdot 1.5 \Rightarrow \mathbf{F_{sp} = 4500 \text{ N}}$$

Initial clamping force during shutdown:

$$F_{sp0} = S_{sp} \cdot (F_{sp} + F_c)$$

Calculation of total centrifugal force:

$$F_c = \sum M_c \cdot \left(\frac{\pi \cdot n}{30}\right)^2$$

For two-part chuck jaws, the following applies:

$$M_c = M_{cGB} + M_{cAB}$$

Take the centrifugal torque of the base jaw and top jaw specified from the "Lathe chuck data" table:

$$\mathbf{M_{cGB} = 0.319 \text{ kgm}}$$

For the centrifugal torque of the top jaw, the following applies:

$$M_{CAB} = m_{AB} \cdot r_{sAB} = 5.33 \cdot 0.107 \Rightarrow \mathbf{M_{CAB} = 0.57 \text{ kgm}}$$

Centrifugal torque for one jaw:

$$M_c = 0.319 + 0.571 \Rightarrow \mathbf{M_c = 0.89 \text{ kgm}}$$

The chuck has 3 jaws, the total centrifugal torque is:

$$\sum M_c = 3 \cdot M_c = 3 \cdot 0.889 \Rightarrow \mathbf{\sum M_c = 2.667 \text{ kgm}}$$

The total centrifugal force can now be calculated:

$$F_c = \sum M_c \cdot \left(\frac{\pi \cdot n}{30}\right)^2 = 2.668 \cdot \left(\frac{\pi \cdot 1200}{30}\right)^2 \Rightarrow \mathbf{F_c = 42131 \text{ N}}$$

Initial clamping force during shutdown that was sought:

$$F_{sp0} = S_{sp} \cdot (F_{sp} + F_c) = 1.5 \cdot (4500 + 42131) \Rightarrow \mathbf{F_{sp0} = 69947 \text{ N}}$$

### 3.3.3 Calculation of the permissible speed in case of a given initial clamping force

**Calculation of the permissible RPM  $n_{perm}$  in case of a given initial clamping force  $F_{sp0}$**

The following formula can be used to calculate the permissible RPM for a given initial clamping force during shutdown:

$$n_{zul} = \frac{30}{\pi} \cdot \sqrt{\frac{F_{sp0} - (F_{spz} \cdot S_z)}{\sum M_c}} \quad [\text{min}^{-1}]$$

#### CAUTION

**For safety reasons, the calculated permissible RPM may not exceed the maximum RPM inscribed on the lathe chuck!**

#### Example of calculation: Permissible RPM for a given effective clamping force

The following data is known from previous calculations:

- Initial clamping force during shutdown  $F_{sp0} = 17723 \text{ N}$
- Machining force for machining job  $F_{spz} 3000 \text{ N}$  (application-specific)
- Total centrifugal torque of all jaws  $\sum M_c = 2,668 \text{ kgm}$
- Safety factor  $S_z = 1.5$  (according to VDI 3106)
- Safety factor  $S_{sp} = 1.5$  (according to VDI 3106)

#### NOTE:

Masses of the jaw mounting screws and T-nuts are not taken into account.

Identifying the permissible RPM:

$$n_{zul} = \frac{30}{\pi} \cdot \sqrt{\frac{F_{sp0} - (F_{spz} \cdot S_z)}{\sum M_c}} = \frac{30}{\pi} \cdot \sqrt{\frac{69947 - (3000 \cdot 1.5)}{2.668}} \Rightarrow \mathbf{n_{zul} = 1495 \text{ min}^{-1}}$$

The calculated RPM  $n_{perm} = 1495 \text{ RPM}$  is smaller than the maximum permissible RPM of the lathe chuck  $n_{max} = 3200 \text{ RPM}$  (see "Lathe chuck data" table ▶ 3.1 [17]).

**This calculated RPM may be used.**

### **3.4 Grades of Accuracy**

Tolerances for radial and axial run-out accuracy correspond to the Technical Supply Terms for lathe chucks as per DIN ISO 3442-3.

### **3.5 Permissible imbalance**

The ROTA THW plus in ungreased state without top jaws corresponds to the balancing quality class 6.3 (according to DIN ISO 21940-11). Residual imbalance risks may arise due to insufficient rotation compensation being achieved (see DIN EN ISO 21940-11). This applies particularly to high RPM, asymmetrical workpieces or the use of various top jaws, as well as uneven lubrication. In order to prevent damage resulting from these residual risks, the entire rotor must be dynamically balanced in accordance with DIN ISO 21940-11.

## 4 Attachment and disassembly of the chuck

The item numbers specified for the corresponding individual components relate to the chapter Drawings, ▶ 10 [ 40].

### 4.1 Torques per screw

**Tightening torques for mounting screws used to clamp the chuck on lathes or other suitable technical equipment (screw quality 10.9)**

Screw size	M6	M8	M10	M12	M14	M16	M18	M20	M22	M24	M27	M30
Admissible torque $M_A$ (Nm)	13	28	50	88	120	160	200	290	400	500	1050	1500

**Tightening torques for mounting screws used to attach top jaws onto the chuck (screw quality 12.9)**

Screws for base jaws GB / GBK / GBK-V / GBKL	M6	M8	M10	M12	-	M16	M20	-	M24
Admissible torque $M_A$ (Nm)	16	25	60	80	-	100	180	-	230

### 4.2 Pre-assembly measures

Carefully lift the product (e.g. using suitable lifting gear) from the packaging.



#### ⚠ CAUTION

**Danger of injury due to sharp edges and rough or slippery surfaces**

Use personal protective gear, especially safety gloves.


Check the delivery for completeness and for transport damage.

### 4.3 Mounting of the Chuck to the Machine Spindle

#### Checking the chuck mounting

- Check the machine spindle nose and ready-machined intermediate flange for centricity and axial run-out. The permissible limit is 0.005 mm as per DIN 6386-1.
- The contact surface must be chamfered and clean at the bore holes.

### Mounting the ROTA THW plus chuck




Chuck assembly

### Maximum attainable radial and axial run-out tolerances related to the chuck

Chuck size [mm]	Max. radial run-out tolerance [mm]	Max. axial run-out tolerance [mm]
165	0.02	0.02
185	0.02	0.02
215	0.02	0.02
260	0.03	0.03
315	0.03	0.03

### Assembly procedure

- Move the draw tube to its foremost position by actuating the clamping cylinder.



### Piston in foremost position

R1 = Push the chuck piston to its foremost position and measure with a depth gauge

R2 = R1 + 0.3 mm (max. + 0.5 mm)

**You have to ensure that the piston can be moved to the foremost (jaw change) position. To do this, ensure that the dimensions for the attachment are complied with.**

- Move the chuck piston (item 3) to its foremost position.

### Chucks in sizes 165, 185 and 215


- Offset the base jaws so that they do not project over the outer edge of the chuck.
- The entire chuck has to be rotated on the draw tube (rod).
- Insert and **slightly tighten** the mounting screws.
- Check the chuck for radial and axial run-out and, if necessary, align it at the outer diameter with gentle taps using a plastic hammer. (See "Chuck assembly" Fig. – E and the table of the attainable maximum radial and axial run-out tolerances)
- Then tighten the fastening screws alternately with a torque wrench. Observe the specified maximum tightening torques ▶ 4.1 [ 25].
- Check radial and axial run-out again.
- Check the actuating force is functioning and is sufficiently large.
- Move the cylinder into the front position. Unlock the wedge bars with the jaw change key supplied and insert or offset the base jaws into the chuck's jaw guidance as shown on markings 1, 2 or 3.
- Check that the base jaw and jaw stroke can easily move.

### Chucks in sizes 260 and 315

- Offset the base jaws to the outermost marking (► 5.3 [□ 33]).
- Remove the screws (item 43) and use the threaded extraction hole to push off the protection sleeve (item 4) away from the chuck body (item 1), and then pull it out completely.
- Lift the chuck to in front of the spindle lug using an eye bolt flush to the center of the spindle.
- Screw the rotating center sleeve (item 18) onto the draw tube using the enclosed assembly tool as far as this will go.
- Check the chuck for radial and axial run-out and, if necessary, align it at the outer diameter with gentle taps using a plastic hammer. (See "Chuck assembly" Fig. – E and the table of the attainable maximum radial and axial run-out tolerances)
- Then tighten the fastening screws alternately with a torque wrench. Observe the specified maximum tightening torques ► 4.1 [□ 25].
- Check radial and axial run-out again.
- Check the actuating force is functioning and is sufficient.
- Insert and fasten the protection sleeve (item 4) in the chuck body with the screws (item 43).
- Move the cylinder to the front position. Unlock the wedge bars with the jaw change key supplied and insert or offset the base jaws into the chuck's jaw guidance as shown on markings 1, 2 or 3.
- Check that the base jaw and jaw stroke can easily move.

The spindle is disassembled in the same way but in the reverse order.

**At regular intervals, check that the retainer ring (item 17) is seated firmly.**



ROTA THW plus Size	A Thread	B [mm]	C [mm]	D [mm]	E [mm]	F [mm]	O-ring [mm]
165-43	M54 x 1.5	15.0	43	50.8	2.8	47	50.47 x 2.62
185-52	M64 x 1.5	15.0	52	62.0	2.4	58	60 x 2
215-66	M78 x 1.5	17.0	66	76.0	2.4	70	76 x 2
260-81	M90 x 2.0	20.3	81	87.0	2.4	84	86 x 2
315-104	M115 x 2.0	22.5	104	110.0	3.2	107	110 x 3

#### Lubricating before commissioning the lathe chuck

Before commissioning, move the chuck into the open position. Using a high-pressure grease press, press SCHUNK special grease LINOMAX plus into the lubricating nipple every 3 strokes. For optimum grease distribution and to achieve the maximum clamping force, close and open the chuck multiple times over the entire clamping stroke. Check the clamping force and if necessary repeat the lubrication procedure.

#### 4.4 Disassembling and assembling the chuck

The lathe chuck may only be disassembled once it has been uninstalled (see Mounting the chuck, chapter ▶ 4.3 [ 25] ) .

- You can leave the base jaws (item 2) in the chuck. Move them to the outermost permissible position. To do this, push the chuck piston (item 3) to its front end position.

- Remove the screws (item 43) and use the threaded extraction hole to push off the protection sleeve (item 4) away from the chuck body (item 1), and then pull it out completely.
- Remove the screws (item 42/44) from the mount (item 7).
- Mark the position of the mount (item 7) in relation to the chuck body (item 1).
- Undo the screws (item 40/41) several thread turns and hammer gently on the screw heads using a rubber mallet. This allows the mount (item 7) to be released from the centering for the chuck body (item 1). Remove the screws and take off the mount.
- Remove the safety bolt (item 14) with compression spring (item 35) and spring bolt (item 13).
- Use a suitable tool to push out and remove the jaw-change bolt (item 8) with the balls (item 37) through the bore hole for the safety bolt. Check the seal (item 33) for damage and wear, and replace it if necessary.

NOTE: The bearing mechanism may cause metallic noise.

- Pull the chuck piston (item 3) together with the three wedge bars (item 9) out of the chuck body (item 1). The individual wedge bars (item 9) are identified in position in the chuck body (item 1) in accordance with the numbering on the perimeter. The piston has a point marking at the radial front side on the piston wedge hook. This is assigned to base jaw guide 1 during assembly.
- Push the base jaws (item 2) out of the chuck body (item 1).
- Check the seal (item 31) in the chuck piston (item 3) for the protection sleeve (item 4) and the seal (item 32) for the draw tube for damage and wear, and replace it if necessary.
- A wedge bar (item 9) consists of nine parts in total. Spring tension pre-loads the pressure bolt (item 12) and the pressure pieces (item 16). Remove the wedge bar (item 9) using the appropriate safety measures and using safety goggles.
- With its slot for the jaw-change bolt (item 8), the eccentric bolt (item 10) is joined to the wedge bar (item 9) in extension of the groove. This is the position for operation and assembly of the chuck. For disassembly, the eccentric bolt (item 10) has to be turned clockwise by approx. 15° using a suitable tool.
- Push out the eccentric bolt (item 10) from the diagonal pull side of the wedge bar (item 9) up to approx. 6 mm. The thrust bolt (item 12) then becomes visible. The displacement force is reduced through slight pressure on the serration.

- Secure the pressure bolt (item 12) against flying off and then completely remove the eccentric bolt (item 10) out of the wedge bar (item 9).
- Take the angle with plunger pin (item 15) and pressure piece (item 16) with compression spring (item 34) off the wedge bar.
- The pin (item 11) is securely glued into the eccentric bolt (item 10).

Clean all individual components and check them for damage and wear.

**Only original SCHUNK spare parts may be used.**

The lathe chuck is assembled in the same way but in the reverse order.

Before installation, lubricate parts well with LINO MAX plus special grease paste.



**⚠ CAUTION**

**Allergic reactions if lubricating grease comes into contact with the skin.**

- Wear protective gloves.

## 5 Function and handling

The item numbers specified for the corresponding individual components relate to the chapter Drawings, ▶ 10 [ 40].

### 5.1 Function of the chuck

The type THW plus quick-change power chucks are actuated using a rotating solid or through-hole cylinder. The axial tensile or compressive forces are converted to the radial jaw clamping force via wedge bars positioned tangentially to the chuck body.

### 5.2 Handling the chuck and the base jaws

The clamping and opening path of the chuck jaws is prescribed by the clamping cylinder. The base jaws with screwed-on top jaws are moved or changed in the open clamping position. For safety reasons, the serration for the base jaws is still engaged in this chuck piston position. The base jaws are unlocked manually.



#### ⚠ CAUTION

**There is a risk of crushing during manual loading due to the large jaw stroke.**

We recommend automatic loading.

If manual loading is used, set up the jaw position so that there is no risk of injury when inserting the parts. The maximum opening gap must be less than 4 mm when the workpiece is in contact with one of the jaws.

For each jaw guidance, a jaw-change bolt (item 8) with hexagon socket (which can be turned using the jaw change key (item 90)) is arranged on the chuck perimeter. Turning the jaw-change bolt moves the serration for the wedge bar (item 9) axially against spring pressure out of the serration for the base jaw (item 2). In this position, the base jaws can be moved or changed radially inwards or outwards. It is not possible to pull out the jaw change key in this position.

**Der Auslinkschlüssel wird verriegelt, solange keine Spannbacken in den Funktionsbereich gebracht wurden! Der Funktionsbereich bedeutet, dass die Grundbacke im Eingriff der Verzahnung des Winkels ist.**

#### CAUTION

**The chuck piston (item 3) must not be moved so long as the jaw change key (item 90) is located in one of the jaw-change bolts (item 8) for the chuck.**

**Risk of damage to the chuck.**

**CAUTION**

The mechanical system of the chuck is opened when the protection sleeve (item 4) is changed. No chips may penetrate into the mechanical system of the chuck. If no protection sleeve is installed in the chuck, then the chuck must not be actuated and the chuck piston (item 3) must not be moved!  
Risk of damage to the chuck.

**⚠ CAUTION**


Risk of crushing due to mechanical system of the chuck being open when the protection sleeve is being changed.

Do not reach into the open mechanical system of the chuck!  
Wear protective gloves.

**5.3 Base jaw position**

A marking line between the jaw guides is milled on the face side of the chuck. This marking line is the positioning aid for the base jaws or top jaws. The outermost base jaw or monoblock position is reached when the front face of the base jaw or the unsplit top jaw agrees with the marking line in the jaw change position (chuck open).

**It is vital that this jaw position is adhered to so that all teeth are engaged for the force transmission from the wedge bars to the base jaws or top jaws.**

**5.4 Change or supplement of jaws**

Jaws for highest repeatability must be bored and ground in the chuck under clamping pressure.

- When boring and grinding it is important that the boring ring or the boring bolts are clamped **by the top jaws** – and not by the base jaws. Keep base and top jaws screwed together for later tasks.
- Keep the base jaws and top jaws screwed in place for recurring work. Tighten the jaw mounting screws to the specified torque ▶ 4.1 [□ 25].

**Tighten the jaw mounting screws with a torque wrench.**

## 6 Maintenance

### 6.1 Lubrication




#### ⚠ CAUTION

Allergic reactions or irritation due to skin or eye contact with lubricants on the product.

- Wear protective equipment (protective gloves, protective goggles) in case of foreseeable contact with lubricants on the product (e.g. when lubricating or cleaning)

To maintain the safe function and high quality of the chuck, it must be lubricated regularly at the grease nipples (A / item 39) using a high-pressure grease gun with SCHUNK special grease LINOMAX plus. Move the chuck into the open position.



The following number of grease gun strokes must be applied to the chuck at each of the 3 lubrication points:

Chuck Size	165	185	215	260	315	400
Number of strokes	2	2	4	4	4	6

**Lubricate all three segments evenly in order to avoid imbalances.**

For optimum grease distribution, the clamping piston must travel the entire clamping stroke several times after lubrication.

#### Operating conditions

Depending on the operating conditions, the function and clamping force must be checked after a specific period of operation (see ▶ 6.2 [□ 35]). Only use a calibrated gripping force tester (SCHUNK IFT) for measuring during the clamping force test.

### Technical condition

With the smallest possible actuating pressure (hydraulic cylinder), the base jaws should move evenly. This method only provides a limited indication and is no substitute for measuring the clamping force.

If the clamping force has dropped too much, the chuck must be disassembled, cleaned, and relubricated.

**Only use original SCHUNK spare parts when replacing damaged parts.**

## 6.2 Maintenance and lubrication plan

The specified intervals are guide values and must be adjusted by the operator depending on the ambient and operating conditions and the frequency of use of the clamping device used. In order to determine a suitable lubrication interval for the respective application, it is recommended to carry out a regular clamping force test. If only 80% of the maximum clamping force is reached, the clamping device must be lubricated. In accordance with VDI 3106, it must be ensured that sufficient clamping force is available for the application.

Maintenance task	Strain	Interval
Lubricate	normal / coolant utilization	Daily / every 16 hours*
	high / coolant utilization	1x per shift / every 8 hours*
Check clamping force		To be determined by the operator
Complete cleaning / disassembly	depending on soiling	as required / after 1200 hours

\* Depending on which event occurs earlier.

## 7 Storage

When storing the product for a longer period of time, observe the following points:

- Clean the product and lubricate it lightly.
- Store the product in a suitable transport container.
- Only store the product in dry rooms.
- Protect the product from major temperature fluctuations.

**NOTE:** Before recommissioning, clean the product and all attachments, check for damage, functionality and leaks.

## 8 Disposal

After decommissioning, place the chuck in a position that enables any liquids in the chuck to drain out.

- Collect the escaping liquids and dispose of them properly in line with the statutory provisions.
- Remove any identifiable plastic or aluminum parts installed in or on the chuck and dispose of them properly in line with the statutory provisions.
- Dispose of the chuck's metal parts as scrap metal.

Alternatively, you can return the chuck to SCHUNK for proper disposal.

## 9 Chuck mounts and parts list

### 9.1 Chuck mounts

ROTA THW plus Size	Chuck mount	ID
165-43	Z 140	0800600
	A5	0800601
	A6	0800602
185-52	Z 140	0800610
	Z 170	0800611
	A5	0800612
	A6	0800613
215-66	Z 170	0800620
	A6	0800621
	A8	0800622
260-81	Z 170	0800630
	Z 220	0800631
	A6	0800632
	A8	0800633
315-104	Z 220	0800640
	A8	0800641
	A11	0800642

### 9.2 Parts list

**When ordering spare parts, it is absolutely essential to specify the type, size and above all the manufacturing no of the chuck.**

Seals, sealing elements, screw connections, springs, bearings, screws and wiper bars plus parts coming into contact with the workpiece are not covered by the warranty.

#### ROTA THW plus


Item	Designation	Quantity	Note
1	Chuck body	1	
2	Base jaws	3	
3	Piston	1	
4	Standard protection sleeve	1	
7	Mount	1	
8	Jaw-change bolt	3	
9	Complete wedge bar	3	
10	Eccentric bolt	3	
11	Pin	3	
12	Thrust bolt	3	
13	Spring bolt	3	


Item	Designation	Quantity	Note
14	Safety bolt	3	
15	Plunger pin	3	
16	Pressure piece	6	
17	Retainer ring	1	260 / 315
18	Center sleeve	1	260 / 315
19	Assembly tool	1	260 / 315
20	Lever for assembly tool	1	260 / 315
29	Center sleeve seal	1	260 / 315
31	Piston seal	1	
32	Adapter seal	1	
33	Jaw-change bolt seal	3	
34	Compression spring for pressure piece	6	
35	Compression spring for safety bolt	3	
36	Compression spring for thrust bolt	3	
37	Steel ball for jaw-change bolt	3	
39	Tapered lubricating nipple	3	
40	Mounting screws	3	
41	Mounting screws	3	
42	Mounting screws	3	185 / 215 / 315
	Mounting screws	6	260
43	Mounting screws	3	
44	Mounting screws	3	260
	Mounting screws	6	165 / 185 / 215 / 315
47	Compression spring for grid	2	260 / 315
48	Steel ball for grid	2	260 / 315
60	Eye bolt	1	260 / 315
90	Jaw change key	1	


#### Jaw change key (item 90)

Item	Designation	Quantity	Note
91	Cross handle	1	
93	Holding piece	1	
94	Spring sleeve	1	
95	Pressure sleeve	1	
96	Compression spring	1	

### 10 Drawings









H.-D. SCHUNK GmbH & Co.  
Spanntechnik KG

Lothringer Str. 23  
D-88512 Mengen  
Tel. +49-7572-7614-0  
info@de.schunk.com  
schunk.com

Folgen Sie uns | *Follow us*



Wir drucken nachhaltig | *We print sustainable*

# Manufacturer certificate

**Manufacturer / Distributor:** Heinz-Dieter SCHUNK GmbH & Co. Spanntechnik KG.  
Lothringer Str. 23  
D-88512 Mengen

**Product:** Lathe chuck  
**Description:** ROTA  
**Type designation:** 2B, NCA, NCD, NCE, NC, NCF, NCK, NCO, NCR, NCS, NCX, TH, THW, HSH, HSA, DFF

Heinz-Dieter SCHUNK GmbH & Co. Spanntechnik KG certifies that the above-mentioned products, when used as intended and in compliance with the operating manual and the warnings on the product, are safe according to the national regulations and:

- a **risk assessment** has been carried out in accordance with ISO 12100:2010.
- an **operating manual** for the assembly instructions has been created in accordance with the contents of the Machinery Directive 2006/42/EC Annex I No. 1.7.4.2. and the contents of the provisions of Annex VI of the Machinery Directive 2006/42/EC.
- the relevant basic and proven safety principles of the Annexes of **ISO 13849-2:2012**, taking into account the requirements of the documentation have been observed for the component. The parameters, limitations, ambient conditions, characteristic values, etc. for correct operation are defined in the operating manual.
- an  $MTTF_D$  value of 150 years can be estimated for mechanical components using the informative procedure in Table C.1 of ISO 13849-1:2015.
- the **fault exclusion** against the fault "Unexpected release without pending release signal".
- the **fault exclusion** against the fault "Breakage during operation" in compliance with the parameters, limitations, ambient conditions, characteristic values and maintenance intervals, etc., specified in the operating manual.
- that internal bore diameters in the **pipe or control lines** are at least 2 mm for pneumatic clamping systems and at least 3 mm for hydraulic clamping systems

#### Harmonized standards applied:

- **ISO 12100:2010** Safety of machinery - General principles for design - Risk assessment and risk reduction
- **EN 1550:1997+A1:2008** Machine-tools safety – Safety requirements for the design and construction of lathe chucks for the workpiece mount

#### Other related technical standards and specifications:

- **ISO 702-1:2010-04** Machine tools – Connecting dimensions of spindle noses and lathe chucks – Part 1: front short-taper mount with screws
- **ISO 702-4:2010-04** Machine tools – Connecting dimensions of spindle noses and lathe chucks – Part 4: cylindrical mount
- **VDI 3106:2004-04:** Determination of permissible RPM of lathe chucks (jaw chucks)

Mengen, 02. Aug. 2023

*i. V. Philipp Schröder*

p.p. Philipp Schröder / Head of Development standard products

*i. V. Alexander Koch*

p.p. Alexander Koch / Head of Engineering Design special products